

Suitable to replace Reference(s)

Audi G 055 025 | G 055 025 A2
BMW 83 22 0 402 413 | 83 22 2 220 438 | 83 22 2 355 599 | 83 22 7 542 290 | 83 22 9 407 858
Chrysler ATF +4 | 68218054AB | 68218054CA | 68218056AD | 68218057AA | 68218057AB | 68218057AC | 68218057CA | 68218057CB | 68218057GA | 68218058AC | 68218058CA | 68218058GA | 68218059AC | 68333587AA | ATF +3 | MS-9602
Citroën 9734.R7 | 9980.D4
Dodge 05013458AA | 05013457AA
FIAT TIPO T-IV | 9.55550 | 9.55550-AG2 | 9.55550-AV1 | 9.55550-AV4 | F333.I05
Ford AU7J-19A509-AA | WSS-M2C924-A
Honda 08266-99901 HE | 08200-9005 | 08200-9008 | 08200-9009 | 08266-99904 | 08266-99907 | 08266-99964 | 08266-99967 | 0820899915HE | 0826399951HA | 0826399951HB | 0826599901HA | 0826599901HB | 0826599961HA | 0826699901HA | 0826699901HB
Hyundai NPNEA-TMOIL S1 | 00232-19012 | 00232-19052 | 04500-00100 | 04500-00115 | 04500-00117 | 04500-00400 | 04500-00A00 | NPNSA-TMOIL S1 | SP III | SP IV | SP IV RR
Isuzu ATF 3309
KIA ATF SP-III | NPNSA-TMOIL S1 | NPNEA-TMOIL S1 | UM040-CH020
Land Rover ASW 3309 | LR 002748 | LR 022460
Lexus 08886-80503 S1 | 08886-80506
Mazda 0000-77-114E-0
MINI 83 22 7 542 290 | 83 22 9 407 858 | 83 22 2 355 599
Mitsubishi M2312096 S1 | MS991154 | MS991156 | MS991158 | MZ320016 | MZ320101 | MZ320159 | MZ320160 | MZ320162 | MZ320200 | MZ320216
Nissan Matic S | 999MP-AA100P | 999MP-MTJ00P | 999MP-MTS00P | KE908-99932 | KLE23-00002 | KLE24-00002 | KLE27-00002
Opel 19 40 767 | 19 40 771 | 19 40 773
Peugeot 9734.R7 | 9980.D4 | 9730.AF
Porsche000 043 205 28 | 958 300 540 00 | 958 300 901 00
Renault 77 11 218 368
Saab ATF 3309
Seat G 052 990 | G 055 025 | G 055 025 A2
Škoda G 055 025 | G 055 025 A2
Subaru ATFHP
Suzuki 99000-22800-001
Toyota 08886-80503 S1 | WS | 00279000T4 | 00289-ATFWS | 08886-00405 | 08886-01705 | 08886-02303 | 08886-02305 | 08886-80506 | 08886-80803 | 08886-81015 | 08886-81016 | 08886-81210
Vauxhall 09256039 | 09117946 | 93160393 | 93165147
Volkswagen (VW) G 052 990 | G 052 990 A2 | G 055 025 | G 055 025 A2 | G 055 540 A2
Volvo 1161540 | 1161640 SK | 31256675 | 31256774 | 31256775 | 31256776 | 31325626 | 31325627
General Service Number AISIN WARNER AW-1 | AISIN WARNER/ AW-1 | ATF AW-1 | ATF SP-II | ATF SP-III | ATF SP-II M | ATF T-IV | BMW ATF 6 | Chrysler ATF +4 | Daihatsu Alumix ATF | Dexron III | ELFMATIC J6 | FIAT 9.55550-AV1 | FIAT 9.55550-AV2 | Fiat Typo T-IV | Ford WSS-M2C922-A1 | Ford WSS-M2C924-A | Honda ATF Z-I | Honda DW-1 | Isuzu Besco ATF-II | Isuzu Besco ATF-III | JASO M315 Typ 1A | JWS 3309 | JWS 3314 | JWS 3324 | Kia ATF RED-1K | Kia SP-II | Kia SP-III | Kia SP-IV RR | Mazda ATF D-III | Mazda ATF M-III | Mazda ATF M-V | Mitsubishi SP II | Mitsubishi SP III | Nissan ATF-Matic D | Nissan ATF-Matic J | Nissan C/D/J | Nissan Matic S | Peugeot ATF AW-1 | Saab ATF 3309 | Subaru ATF / Special | Suzuki 3309 | Suzuki 3317 | Suzuki AW-1 | Texaco N402 | Toyota ATF WS | Toyota Type D-2/WS | Toyota Type T-II | Toyota Type T-III | Toyota Type T-IV | Toyota WS | TUTELA GI/E | TUTELA GI/V | TUTELA VI | ZF LGF 6.1 ATF | ZF Lifeguardfluid 6.1 ATF